
## Technical considerations for repeat transcatheter aortic valve implantation in a failing Direct Flow Medical transcatheter heart valve



**Jonathan Yap**, MBBS, MRCP, MPH; Jeffrey A. Southard, MD; Garrett B. Wong, MD; Gagan D. Singh, MD; Benjamin R. Stripe\*, MD

Division of Cardiovascular Medicine, University of California, Davis, CA, USA

This paper also includes supplementary data published online at: https://eurointervention.pcronline.com/doi/10.4244/EIJ-D-20-00426



**Figure 1.** TAVI in Direct Flow Medical valve. Computed tomography (CT) dimensions of ventricular (A) and aortic rings (B). CT showing relationship between the Direct Flow Medical (DFM) valve and the left coronary (C) and right coronary (D) arteries. Benchtop side (E) and aerial (F) profiles of the DFM valve. Benchtop side (G) and aerial (H) profiles of the valve-in-valve. I) Post-dilatation of Evolut R valve. J) Final aortogram of valve-in-valve. TEE short-axis (K) and long-axis (L) view of valve-in-valve with colour Doppler.

<sup>\*</sup>Corresponding author: UC Davis Medical Center, 4860 Y Street, Suite 2820, Sacramento, CA 95817, USA. E-mail: brstripe@ucdavis.edu

Transcatheter aortic valve implantation (TAVI) has increasingly been performed in failing aortic bioprostheses, but these "valve-invalve" procedures are technically more challenging<sup>1,2</sup>. The Direct Flow Medical® (DFM) transcatheter aortic valve (Direct Flow Medical Inc., Santa Rosa, CA, USA) was implanted worldwide<sup>3,4</sup> before its eventual withdrawal from the market. We describe a case of repeat TAVI in a failing DFM valve and discuss the technical considerations involved (no data in the PCR "Valve-in-Valve" app: https://www.pcronline.com/PCR-Publications/PCR-mobile-apps/Valve-in-Valve-Aortic-app).

An 81-year-old female with a history of coronary bypass and pacemaker insertion underwent TAVI for severe aortic valve (AV) stenosis with a 25 mm DFM valve. After the index TAVI, her mean AV gradient improved from 47 mmHg to 18 mmHg. Six years later, she presented with New York Heart Association (NYHA) Class IV symptoms with a decrease in her previously normal ejection fraction (EF) to 35% and severe bioprosthetic aortic stenosis (mean AV gradient 40 mmHg). She was considered high-risk for surgery. Computed tomography (CT) was critical to aid in sizing as well as assessing the risk of coronary obstruction. The two rings of the DFM valve are filled with epoxy-based polymer and the final size may vary. In this case of a 25 mm DFM valve, the average inner diameters were 18.4 mm and 18.2 mm for the ventricular and aortic rings, respectively (Figure 1A, Figure 1B). The coronary ostia originated from above the aortic ring of the DFM valve; as such, the risk of coronary occlusion was assessed as being low (Figure 1C, Figure 1D). Due to the small inner diameter, we chose a supra-annular valve to provide better haemodynamics. Thus, a 23 mm CoreValve® Evolut<sup>TM</sup> R (Medtronic, Minneapolis, MN, USA) was chosen. To understand the ideal deployment of the valve, we obtained a 25 mm DFM valve and implanted a 23 mm Evolut R valve on the benchtop to study the optimal implantation depth (Figure 1E, Figure 1F). As seen from the benchtop models and our clinical case, the base of the Evolut should be positioned in line with the base of the ventricular ring of the DFM (Figure 1G, Figure 1H). Predilatation was performed with a 16 mm balloon and the repeat TAVI procedure was successfully performed under moderate rate control pacing to reduce motion. The Evolut R valve appeared underexpanded on fluoroscopy and there was an initial residual gradient of 15 mmHg. Therefore, post-dilatation was performed with a 20 mm TRUE® balloon (Bard Peripheral Vascular, Tempe, AZ, USA), with optimal results (Figure 11-Figure 1L, Moving image 1-Moving image 4). At one-month follow-up, the patient had NYHA Class II symptoms with a mean valve gradient of 7 mmHg.

## Conflict of interest statement

The authors have no conflicts of interest to declare.

## References

- 1. Noorani A, Bapat V. Valve-in-Valve Therapy for Failed Surgical Bioprosthetic Valves: Clinical Results and Procedural Guidance. *Interv Cardiol Clin.* 2015;4: 107-20.
- Edelman JJ, Khan JM, Rogers T, Shults C, Satler LF, Ben-Dor II, Waksman R, Thourani VH. Valve-in-Valve TAVR: State-of-the-Art Review. *Innovations* (*Phila*). 2019;14:299-310.
- 3. Lefèvre T, Colombo A, Tchétché D, Latib A, Klugmann S, Fajadet J, De Marco F, Maisano F, Bruschi G, Bijuklic K, Nava S, Weissman N, Low R, Thomas M, Young C, Redwood S, Mullen M, Yap J, Grube E, Nickenig G, Sinning JM, Hauptmann KE, Friedrich I, Lauterbach M, Schmoeckel M, Davidson C, Schofer J. Prospective Multicenter Evaluation of the Direct Flow Medical Transcatheter Aortic Valve System: 12-Month Outcomes of the Evaluation of the Direct Flow Medical Percutaneous Aortic Valve 18F System for the Treatment of Patients With Severe Aortic Stenosis (DISCOVER) Study. *JACC Cardiovasc Interv.* 2016;9:68-75.
- 4. Gamal AS, Akleh S, Zaman A, Das R, Abushouk AI, Edwards R. Outcomes of Direct Flow Medical vs Sapien 3 Transcatheter Aortic Valve Devices. *J Cardiovasc Transl Res.* 2019 Dec 17. [Epub ahead of print].

## Supplementary data

**Moving image 1.** Post-dilatation of the Evolut R valve.

Moving image 2. Final aortogram of valve-in-valve.

**Moving image 3.** TEE short-axis view of valve-in-valve with colour Doppler.

**Moving image 4.** TEE long-axis view of valve-in-valve with colour Doppler.

The supplementary data are published online at: https://eurointervention.pcronline.com/doi/10.4244/EIJ-D-20-00426

